

County Surveyor's Record, Douglas County, Oregon

Resurvey of Subdivision Lines of T. 32 S., R. 3 W.

CHAINS	
	Thence I run North, on a random line, bet. Secs. 1 and 2.
40.00	No evidence of old $\frac{1}{4}$ Sec. cor. are found after careful search. Set temp. $\frac{1}{4}$ Sec. cor.
81.40	Intersect N. bdy. of Tp., 20 lks. E. of the cor. of Secs. 1, 2, 35 and 36, which is a granite stone 5x11x7 ins., above ground, firmly set, marked and witnessed as described by the Surveyor General; thence I run S.0°8'E., on a true line, bet. Secs. 1 and 2. Over mountainous land, heavily timbered and covered with dense undergrowth. Descend SE. slope.
20.00	Ravine, C. SE.
28.50	Creek, 5 lks. wide, C. SW.
40.70	Set a slate stone 18x12x4 ins., 12 ins. in the ground, for $\frac{1}{4}$ Sec. cor., marked $\frac{1}{4}$ on W. face, from which A Fir, 18 ins. diam., bears S.34°E., 40 lks. dist., marked $\frac{1}{4}$ S 1 B T. A Madrone, 12 ins. diam., bears S.81°W., 22 lks. dist., marked $\frac{1}{4}$ S 2 B T.
45.00	Summit of ridge, bears NE. and SW. Leave heavy timber. Descend S. slope.
51.50	Creek, 1 lk. wide, C. SW.
81.40	The cor. of Secs. 1, 2, 11 and 12. Note: The SE. bearing tree at this cor. reported in my original description of re-establishment at 200 lks. dist. is found to be 251 lks. dist. Land, mountainous. Soil, loam and stony; second and third rate. Timber, Fir, Pine, Cedar and Madrone. Undergrowth, Madrone, Hazel, Arrpwood, Lilac and Manzanita. Mountainous or heavily timbered land, or land covered with dense undergrowth, 81.40 chs.

November 15, 1907