

County Surveyor's Record, Douglas County, Oregon

Extension Survey of the Subdivision of T. 32 S., R. 3 W.

CHAINS

East, on a random line, bet. secs. 22 and 27.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

79.80 Intersect N. and S. line, 23 lks. S. of the cor. of secs. 22, 23, 26 and 27.

Thence I run

S. 89° 50' W., on a true line, bet. secs. 22 and 27.

Along S. slope, through scattering timber and undergrowth.

5.65 Creek, 1 lk. wide, course SW. Leave dense undergrowth, bears NE. and SW.

15.00 Flat spur, slopes SW. Gradually descend SW. slope.

33.30 Red Mountain trail, bears NE. and SW.

33.80 Begin steep, rocky descent from Red Mountain on NW. slope.

39.90 Set a serpentine stone, 18x10x8 ins., 12 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N. face; from which

A cedar, 6 ins.diam., bears N. 2° W., 38 lks. dist., marked $\frac{1}{4}$ S 22 B T.

A cedar, 8 ins.diam., bears S. 40° W., 56 lks. dist., marked $\frac{1}{4}$ S 27 P T.

54.00 Foot of steep descent.

Enter dense undergrowth, bears NE. and SW. Gradually descend W. slope.

70.90 Creek, 1 lk. wide, course SW.

79.00 Creek, 1 lk. wide, course NW.

79.80 The cor. of secs. 21, 22, 27 and 28.

Land, mountainous.

Soil, to 54.00 chs. stony clay loam and serpentine rock 4th rate; to 79.80 chs. decomposed granite; 3rd rate.

Timber, fir, yellow pine and cedar.

Undergrowth, snow brush, rhododendron, hemlock and fir.

October 10, 1913.

October 17: At the cor. of secs. 21, 22, 27 and 28.

Thence I run

N. 0° 2' W., bet, secs. 21 and 22.

Descend NW. slope, through scattering timber and dense undergrowth.