

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 32 S., R. 4 W.

CHAINS

There is a saw mill in Sec. 7, and many other as good or better mill sites along the creek above with good timber in great abundance on either side.

7th Stand. Parallel S., R. 4 W.
As surveyed by McKenzie and Eckelson, Deputy Surveyors
Under Contract No. 328, dated June 17, 1879

West bet. secs. 1 and 36, Tps. 32 and 33, S., R. 4 W.

* * * * *

80.00 Set post for corner to secs. 35 and 36, from which,
A Laurel, 7 ins. diam., N.18*45'E., 38 lks. dist.
A Laurel, 8 ins. diam., N.40*30'W., 39 lks. dist.
County, mountainous. No vegetation.
Timber, B. Pine, S. Pine, Yew and Laurel.

West bet. secs. 2 and 35.

Va. 18*E.

2.00 Top of high ridge, C. NE. and SW.
15.00 Small stream, 6 lks. wide, flows S.40*W.
40.00 Set post for 1/2 sec. corner, from which,
A Laurel, 6 ins. diam., S.50*E., 47 lks. dist.
A Fir, 7 ins. diam., N.45*W., 25 lks. dist.
60.50 Top of high ridge, runs N. and S.
80.00 Set post for corner to secs. 34 and 35, from which,
A Fir, 18 ins. diam., N.40*W., 17 lks. dist.
A Fir, 24 ins. diam., N.32*50'E., 40 lks. dist.
Country, mountainous. Much brush.
Timber, Fir, Pine, and Hemlock.
Land, third grade.

West bet. secs. 3 and 34.

Va. 18*50'E.

3.00 Small stream, flows S.80*W., 4 lks. wide.