

Subdivisions, T. 32 S., R. 4 W.

CHAINS

7.02

To the corner marked for Ts. 32 and 33 S., Rs. 4 and 5 W., which I reestablish as follows:

Set a basalt sone, 12 x 12 x 8 ins., 8 ins. in the ground for corner of Ts. 32 and 33 S., R 5 W., marked with 6 notches on N. and W. edges; from which,

A fir, 12 ins. diam., bears S. 48* W., 22 lks. dist., marked T. 33 S., R. 5 W., S. 1, B. T.

A Fir, 12 ins. diam., bears N.85*W., 20 lks. dist., marked T. 32 S., R. 5 W., S. 36, B. T.

This corner is on the NW. slope of mountain, about 200 ft. below SW. corner of T. 32 S., R. 4 W.; I reestablished it at same point.

Land, mountainous.

Soil, fourth rate.

Timber, Fir, Pine, Cedar, Madrona, Hemlock, Maple, Yew and Alder.

Dense undergrowth of Vine Maple, Huckle-berry, Salal-berry, Rhododendron, and Ocean-spray.

Land, mountainous, heavily timbered or covered with dense undergrowth, 7.02 chs.

East on blank line, on S. bdy. of sec. 31.

37.84

To $\frac{1}{4}$ sec. corner on S. bdy. of sec. 31, which is a post 3 ins. sq., 24 ins. above ground, marked and witnessed as described by the surveyor general.

Aug. 20: At this $\frac{1}{4}$ sec. corner, I set off 12*11'N. on the decl. arc; and at o h. 3 m., p.m., l.m.t., observe the sun on the meridian, the resulting lat. is 42*44'N., which is practically correct.

77.09

To a point, 8 lks. N. of standard corner of secs. 31 and 32, which is a post badly decayed; bearing trees standing and agreeing with the description of the surveyor general. I reestablish this corner at the same point as follows: