

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 32 S., R. 4 W.

CHAINS

This corner is on NW. slope of spur, 350 ft. below top. Land, mountainous.  
 Soil, third and fourth rate.  
 Timber, Fir, Cedar, Hemlock, Maple.  
 Dense undergrowth of Rhododendron, Vine-Maple, Mountain-Balm, Huckle-berry, Chinquapin, Hazel and Salal-berry.  
 Mountainous land, heavily timbered or covered with dense undergrowth, 79.73 chs.

---

From the  $\frac{1}{4}$  sec. corner, bet. secs. 2 and 3, which is a post 20 ins. above ground, marked and witnessed as described by the surveyor general, I run  
 South on a true line, bet. secs. 2 and 3.  
 Asc. spur.

- 3.50 Top of spur, slopes E., 50 ft. above  $\frac{1}{4}$  sec. corner; desc.
  - 13.52 Creek, 3 lks. wide, C. E., 200 ft. below top of last spur; asc. spur.
  - 21.80 Top of spur, slopes E. 150 ft. above creek; desc. into canyon.
  - 28.00 Bottom of canyon, 150 ft. below top of spur; asc. spur.
  - 35.04 Intersect E. and W. line, 531 lks. S.89\*50'E. of the temp. corner of secs. 2, 3, 10 and 11.  
 Set a Madrona post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for closing corner of secs. 2 and 3, marked C. C. T. 32 S., R. 4 W., on N., S. 2 on E., and S. 3 on W., with 2 grooves on E. faces; from which  
     A Fir, 12 ins. diam., bears N.77\*E., 33 lks. dist., marked T. 32 S., R. 4 W., S. 2, B. T.  
     A Fir, 6 ins. diam., bears N.63\*W., 9 lks. dist., marked T. 32 S., R. 4 W., S. 3, B. T.
- This corner is on the NE. Slope of spur, 150 ft. above bottom of canyon.  
 Land, mountainous.  
 Soil, fourth rate.