

County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 32 S., R. 4 W.

CHAINS

72.50 Ravine, C. SW., 25 ft. below top of spur.

80.00 Set a Fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for corner of secs. 15, 16, 21 and 22, marked T. 32 S., S. 15 on NE., R. 4 W., S. 22 on SE., S. 21 on SW., and S. 16 on NW. faces, with 3 notches on S. and E. edges; from which

A Madrona, 12 ins. diam., bears N.70°E., 46 lks. dist., marked T. 32 S., R. 4 W., S. 15, B. T.

A Fir, 16 ins. diam., bears S.60°E., 67 lks. dist., marked T. 32 S., R. 4 W., S. 22, B. T.

A Fir, 14 ins. diam., bears S.34°W., 30 lks. dist., marked T. 32 S., R. 4 W., S. 21, B. T.

A Fir, 12 ins. diam., bears N.63°W., 33 lks. dist., marked T. 32 S., R. 4 W., S. 16, B. T.

This corner is on the SW. slope of mountain, 100 ft. above ravine.

Land, mountainous.

Soil, third and fourth rate.

Timber, Fir, Cedar, Pine, Hemlock, Madrona, Yew and Maple.

Dense undergrowth of Rhododendron, Vine-Maple and Salal-berry.

Land, mountainous, heavily timbered or covered with dense undergrowth, 80.00 chs.

40.00 South, 89°52'E., on a random line bet. secs. 15 and 22. Set a temp. $\frac{1}{4}$ sec. corner.

79.68 Intersect N. and S. line, 21 lks. N. of the corner of secs. 14, 15, 22 and 23; thence, I run North, 89°43'W. on a true line, bet. secs. 15 and 22. Leave green timber, bears N. and S.

2.50 Begin steep descent.

Enter green timber, bears N. and S.