

## County Surveyor's Record, Douglas County, Oregon

Subdivisions, T. 32 S., R. 4 W.

CHAINS

A Madrona, 8 ins. diam., bears S.85\*W., 18 lks.  
dist., marked T 32 S R 4 W S 20 B T.

A Madrona, 6 ins. diam., bears N.81\*W., 21 lks.  
dist., marked T 32 S R 4 W S 17 B T.

This corner is on the S. slope of spur, 200 ft. above  
ravine.

Land, mountainous.

Soil, third and fourth rate.

Timber, Fir, madrona, pine, yew and maple.

Dense undergrowth of rhododendron, mountain-balm, hazel,  
salal-berry, madrona and ocean-spray.

Mountainous land, heavily timbered or covered with  
dense undergrowth, 80.00 chs.

September 4, 1897

---

At the corner of secs. 16, 17, 20 and 21

I run

South, 89\*56'E., on a random line, bet. secs. 16 and 21.

40.00 Set a temp.  $\frac{1}{4}$  sec. corner.

80.18 Intersect N. and S. line, 24 lks. N. of corner of  
secs. 15, 16, 21 and 22.

Thence, I run

North, 89\*46'W. on a true line, bet. secs. 16 and 21.

Desc.

10.25 Ravine, C. S., 100 ft. below sec. corner; asc. spur.

13.75 Top of spur, slopes S., 50 ft. above last ravine;  
desc.

20.25 Ravine, C. S., 75 ft. below last spur; asc. spur.

20.75 Top of spur, slopes S., 20 ft. above last ravine; desc.

21.75 Ravine, C. S., 25 ft. below top of last spur; asc. spur.

28.75 Top of spur, slopes S., 50 ft. above last ravine; desc.