

Subdivisions, T. 32 S., R. 4 W.

CHAINS

Sept. 2, 1897,

I run

West, on a blank line, on the S. bdy. of sec. 4.

39.36

To a point, 24 lks. N. of the $\frac{1}{4}$ sec. corner; post destroyed; bearing trees standing, from which, I reestablish this corner as follows:

Set a fir post 3 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. corner, marked $\frac{1}{4}$ S on N. face; from which

A Fir, 10 ins. diam., bears N.22*W., 30 lks. dist., marked $\frac{1}{4}$ S B T.

A Fir, 40 ins. diam., bears South, 7 lks. dist., marked $\frac{1}{4}$ S B T.

Therefore, this line bears S.89*39'W.

From this $\frac{1}{4}$ sec. corner, I run

West on a blank line.

39.49

To a point, 42 lks. N. of the corner of secs. 4, 5, 8 and 9, which is a post 4 ins. sq., marked and witnessed as described by the surveyor general. I reestablish this corner as follows:

Set a fir post, 4 ins. sq., 4 ft. long, 24 ins. in the ground for corner of secs. 4 and 5, marked

T 32 S S 4 on NE., and R 4 W S 5 on NW. faces, with 4 notches on E. edge; from which

A Cedar, 16 ins. diam., bears N.40*E., 56 lks. dist., marked T 32 S R 4 W S 4 B T.

A Fir, 40 ins. diam., bears N.45*W., 43 lks. dist., marked T 32 S R 4 W S 5 B T.

Therefore, this line bears

South, 89*24'W.

At the corner of secs. 4 and 5, I run

North, 89*30'W. on a blank line, on the S. bdy. of sec. 5.