

County Surveyor's Record, Douglas County, Oregon

West Bdy. of T. 32 S., R. 5 W.

CHAINS

Note:

The above wide closing must be accounted for in the fact that the meridian line was run over a very rough mountain country, while most part of the above line was over very fair chaining.

I think the error a uniform difference in chaining.

W. Lake.

North, on the West Bdy. of sec. 31.

Va. 18*30'E

Witness trees to closing cor.

A Laurel, 4 ins. diam., bears N.15*E., 12 lks.

A Laurel, 4 ins. diam., bears N.82*W., 16 lks.

6.23

A Fir, 26 ins. diam.

18.00

A branch, 3 lks. wide. C. NW.

-180

25.00

Along NW. slope to summit of ridge SE.

+80

40.00

Set qr. sec. post, from which (Va. 18*15'E.)

-120

A Fir, 4 ins. diam., bears S.40*W., 10 lks.

A Yew, 8 ins. diam., bears N.64*E., 14 lks.

40.75

A branch, 5 lks. wide, C. N NE.

56.00

Enter creek bottom, C. N.

-25

59.10

A Fir, 38 ins. diam.

80.00

Set post, cor. to secs. 25, 30, 31 and 36, on creek

Lev.

bottom, from which

A Laurel, 5 ins. diam., bears N.30*30'E., 164 lks.

A Laurel, 4 ins. diam., bears N.43*W., 64 lks.

A Laurel, 4 ins. diam., bears S.38*W., 62 lks.

A Fir, 6 ins. diam., bears S.61*E., 33 lks.

Surface sloping North to creek.

Timber, Fir, with dense undergrowth of Fir, Hazel, Vine Maple, Salal and Manzanita.

Soil, good 2nd rate; clay loam.

Some quartz and slate rock in ravines.

Indications of gold.