

10
County Surveyor's Record, Douglas County, Oregon

West Bdy. of T. 32 S., R. 5 W.

CHAINS

A Fir, 5 ins. diam., bears S.63 $\frac{1}{2}$ *E., 34 lks.
Surface, mountainous and broken.
Third rate stony and gravelly soil.
Timber, Fir, Cedar, Laurel, with undergrowth of same.

North, on the West bdy. of sec. 6.

Var. 19*00'E.

8.39	A Fir, 48 ins. diam.	-25
12.00	Spur of mountain, course E.	+40
19.80	Ravine and branch, 1 lk. wide, S.70*W.	-20
29.00	Summit on line of high ridge, N.80*E.	+100
40.00	Set qr. sec. post on N. slope, (Var.18*50'E.)	-150
	from which	
	A Chinquapin, 8 ins. diam., bears N.52*E., 3 lks.	
	A Fir, 8 ins. diam., bears West, 20 lks.	
47.85	Branch, course N.80*E.	-200
52.08	A Sugar Pine, 36 ins. diam.	+40
54.50	Branch, 2 lks. wide, course E.	-40
70.25	Summit on line of spur.	+100
75.80	To Tp. cor.	-200

Line runs over ridges and ravines along E. slope of mountain ridge.

Timber, Fir, Pine, Laurel, Chinquapin, and Hemlock.
Undergrowth, Fir, Lilac, Gooseberry and Laurel.
Soil, 3rd rate and stony, unfit for settlement.

General Description

This line commences on the North slope of mountains about one mile South of the Valley of Cow Creek, crosses the valley and extends into the canyon mountains on the North. Cow Creek Valley at this point