

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 32 S., R. 5 W.

CHAINS		
	Timber, Fir, Pine, Oak, Maple, Alder, etc. Vine Maple, Willow on bottom, and Fir, Chinquapin and Hazel undergrowth on mountain.	
	S.89*45'E., on random bet. secs. 22 and 27. <div style="text-align: right;">Va. 18*30'E.</div>	
40.00	Set temp. $\frac{1}{2}$ sec. post.	
80.40	Intersect E. bdy. at post.	
	N.89*45'W., on true line bet. secs. 22 and 27. <div style="text-align: right;">Va. 18*30'E.</div>	
19.50	A branch, 3 lks. wide. C. N.	Level
32.00	Begin steep brush ascent of SE. slope of mountain.	+50
40.20	Set $\frac{1}{4}$ sec. post, from which	+175
	A W. Oak, 2 ins. diam., bears N.13*E., 85 lks.	
	A W. Oak, 8 ins. diam., bears S.30*W., 135 lks.	
53.00	Summit of line on ridge, C. NE.	+120
60.00	A Ravine, C. N.	-75
65.00	Summit on spur, C. N.	+85
76.50	Head of ravine, C. N.	-75
79.00	Summit on spur, C. N.	+60
80.40	To sec. cor.	
	Surface broken and mountainous. West half on steep descent to the N. crossing many ravines. East half slopes Eastward. Timber, Fir, some Pine, Oak and Laurel. Dense undergrowth of Fir, Vine Maple, Oak, Laurel, etc. Soil 2nd rate and stony on mountain.	
	North, bet. secs. 15 and 16. <div style="text-align: right;">Va. 18*20'E.</div>	
20.00	Low ridge, C. SW.	+75
24.79	A Y. Pine, 24 ins. diam.	-20
27.00	A Trail. C. N.20*E.	-10