

25

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 32 S., R. 5 W.

CHAINS		
54.25	Jacksonville road, E. & W.	-75
55.00	Enter timber, brush and Cow Cr. bottom, E. & W.	-10
60.00	A slough, 25 lks. wide. C. E. & W.	
62.50	Intersect a part of Cow Cr. C. N.40*W.	
64.75	Right bank of Cow Cr. 1 ch. wide, C. S.75*W.	
75.80	A Slough, 20 lks. wide. C. W.	
80.00	Set Post Cor. to Secs. 20, 21, 28 and 29, from which	Lev.
	A Fir, 8 ins. diam. bears S.8*E., 18 lks.	
	A Fir, 8 ins. diam. bears S.37*W., 40 lks.	
	A Fir, 3 ins. diam. bears N.45*W., 26 lks.	
	A Maple, 3 ins. diam. bears N.62*E., 26 lks.	
	N. of road high hills with Pine and Oak openings.	
	Soil 2nd rate. Creek bottom level with 1st rate loam soil.	
	Dense growth of Balm, Maple, V. Maple, Alder, etc.	
S.89*45'E. on random bet. secs. 21 and 28.		
Va. 19*15'E.		
40.00	Set temp. qr. sec. post.	
80.63	Intersect N. & S. line, 36 lks. N. of post.	
	N.89*30'W. on true line bet. secs. 21 and 28.	
.88	Head of Ravine, C. N.20*E.	-10
5.38	Summit of ridge, C. N.25*E.	+100
19.13	Bottom of steep descent of W. slope.	-300
40.31	Set qr. sec. post, from which	-100
	A Y. Pine, 30 ins. diam. bears N.61*W., 23 lks.	
	A Cedar, 24 ins. diam. bears S.76*E., 32 lks.	
64.13	Dry bed of Branch, 4 lks. wide, C. N.	
80.63	To sec. Cor.	-20
	E. half mountainous and unfit for settlement.	
	Timber Fir and Pine.	
	Undergrowth Fir, and Hazel.	
	Soil, 2nd rate and stony.	
	W. $\frac{1}{2}$ level bottom with dense V. maple thicket.	
	Soil, 1st rate.	