

29

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 32 S., R. 5 W.,

CHAINS		Lev.
58.40	Leave Cow Creek bottom.	Lev.
61.90	Summit of line on N. side of Butte.	+40
64.60	Perpendicular ledge, 35 ft. high N.60*W.	-35
65.15	Left bank of Cow Creek. C. N.60*W.	
65.90	Right bank of Cow Creek. C. N.60*W.	
70.90	Right bank of Cow creek. C. W.	
77.40	Along right bank of Creek.	
78.65	Left bank of Cow creek. C. S.60*W. Banks 4 ft. high. Water 2 ft. deep.	
82.40	To sec. cor. On Cow Creek bottom, nearly level intersecting the creek at several points. Pine, Oak, Ash and Maple timber. V. Maple, Willow, Alder, Thorn and Elder, undergrowth. Soil 1st rate vegetable loam.	Level
S. bet. secs. 29 and 30.		
Va. 18*25'E.		
40.00	Set Cr. sec. post, from which A Cedar, 9 ins. diam. bears N.60*E., 8 lks. A Cherry, 5 ins. diam. bears N.51*W., 26 lks.	+30
50.00	Summit of line on W. slope.	+50
76.75	A Branch, 10 lks. wide. C. N.20*W.	-20
80.00	Set post cor. to secs. 29, 30, 31 and 32 on NE. slope, from which A Maple, 12 ins. diam. bears N.33*W., 16 lks. A Maple, 4 ins. diam. bears S.41*W., 31 lks. A Dogwood, 4 ins. diam. bears S.67½*E., 41 lks. A Fir, 16 ins. diam. bears N.46*E., 25 lks. This mile descends gently to the SW. and has a heavy growth of Fir, Maple, Yew and Balm timber. Dense undergrowth of Laurel, V. Maple, Hazle, Yew, etc. Soil, good 2nd rate, and in part 1st rate clay and loam.	