

32  
County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 32 S., R. 5 W.,

CHAINS		
	S.89*45'E. on random bet. secs. 29 and 32.	
40.00	Set temp. qr. sec. post.	
79.86	Intersect N. & S. line, 52 lks. S. of Post.	
	S.89*53'W. on true line bet. secs. 29 and 32.	
5.00	Ravine and Branch, 1 lk. wide. C. NE.	-50
25.00	Summit of high ridge. C. N.20*E. Enter dense brush, dead from fire.	+350
39.93	Set Qr. sec. post, from which	-175
	A Laurel, 10 ins. diam. bears S.80*W., 32 lks.	
	A Laurel, 4 ins. diam. bears N.20*W., 41 lks.	
42.00	A Ravine. C. SW.	-25
53.50	Spur of mountain. C. NE. to mountain.	+80
66.00	Leave brush and enter timber and brush.	-200
78.00	Branch, 10 lks. wide. C. N.20*W.	-100
79.00	Begin steep ascent.	+5
79.86	To sec. cor.	+25
	Surface very broken and mountainous with poor 3rd rate stony and rocky soil unfit for cultivation.	
	Pine, Fir, Laurel and Dogwood timber, with dense undergrowth of Laurel, Lilac, etc.	
	N.89*45'W. on random line bet. secs. 30 and 31.	
40.00	Set temp. Qr. sec. post.	
82.48	Intersect W. bdy., 20 lks. N. of post.	
	S.89*54'E. on true line bet. secs. 30 and 31.	
4.70	A Branch, 5 lks. wide. C. N.	-25
26.50	Summit of ridge. C. N.80*W.	+175
38.50	A Ravine. C. N.50*W.	-50
42.48	Set Qr. sec. post, from which	+25
	A Cedar, 11 ins. diam. bears S.62½*W., 125 lks.	
	A Cedar, 18 ins. diam. bears N.18*W., 166 lks.	
53.50	Summit of ridge. C. N.20*E.	+300
82.48	To sec. Cor.	-550
	Broken mountain unfit for cultivation.	
	Timber mostly Fir, some Pine, Oak, Laurel and Dogwood.	
	Dense undergrowth of Hazle, Laurel, Dogwood, etc.	
	Soil 3rd rate and stony.	