

Subdivisions of T. 32 S., R. 5 W.

CHAINS		
	<p>A Live Oak, 8 ins. diam., bears N.30*E., 33 lks.</p> <p>A Live Oak, 6 ins. diam., bears S.70*E., 10 lks.</p> <p>A Live Oak, 6 ins. diam., bears S.75*W., 22 lks.</p> <p>A Live Oak, 6 ins. diam., bears N.22*W., 23 lks.</p> <p>Land good 2nd rate, rolling.</p> <p>Timber, 1st rate, Fir, Pine, Cedar, Maple, Ash, Laurel and Oak, but little underbrush, same and Vine maple.</p>	
	<p>North, bet. secs. 25 and 26.</p> <p style="text-align: right;">Va. 19*E.</p>	
7.00	Top of spur. C. W.	+300
19.50	A creek, 5 lks. wide. C. W., mining in creek.	-300
25.00	A Wood Road. C. W. Sept. 13, 1871.	-100
40.00	Set $\frac{1}{4}$ sec. post, from which	00
	A Fir, 10 ins. diam., bears N.28*W., 22 lks.	
	A Laurel, 8 ins. diam., bears S.58*E., 26 lks.	
42.00	Enter brush.	
80.00	Set post, cor. to secs. 23, 24, 25 and 26, from which	+700
	A Laurel, 5 ins. diam., bears N.88*E., 19 lks.	
	A Laurel, 6 ins. diam., bears S.30*E., 75 lks.	
	A Fir, 36 ins. diam., bears S.80*W., 47 lks.	
	A Laurel, 5 ins. diam., bears N.35*W., 20 lks.	
	Land 1st rate along creek, 2nd rate N. of $\frac{1}{4}$ sec post, 3rd rate S. of creek.	
	Timber, good on S. part, 3rd rate on N. part, Fir, Cedar, Pine, Laurel, Oak, etc.	
	Underbrush very thick on N. part, mostly Oak and Laurel.	
	<p>East, on random line bet. secs. 24 and 25.</p> <p style="text-align: right;">Va. 19*E.</p>	
40.00	Set temp. $\frac{1}{4}$ sec. post.	
80.00	Intersect Township line. Timber witness trees and post burned.	