

37  
County Surveyor's Record, Douglas County, Oregon

~~8584~~  
8583  
28

Subdivisions of T. 32 S., R. 5 W.

CHAINS		
	<p>a ridge, excepting at both ends. Timber, good 2nd rate, Fir, Pine, Oak, Laurel, etc. Underbrush same and Hazel and Vine Maple.</p>	
	<p>North, on a random line bet. secs. 26 and 27. <span style="float: right;">Va. 19°E.</span></p>	
40.00	Set temp. $\frac{1}{4}$ sec. post.	
77.97	Intersect line, 600 lks. E. of post, cor. to secs. 22, 23, 26 and 27, from thence S.4°17'E., on a true line bet. secs. 26 and 27.	
37.97	Set $\frac{1}{4}$ sec. post, from which A Pine, 5 ins. diam., bears N.30°W., 91 lks. A Laurel, 5 ins. diam., bears N., 92 lks.	50
77.97	The cor. to secs. 26, 27, 34 and 35. Land level, gravelly bottom land 2nd rate. Timber, 3rd rate, Pine and Fir. Underbrush, Vine Maple and Hazel. <span style="float: right;">Sept. 15, 1871</span> I reexamined this line October 21, 1871.	100
	<p>Being too smoky to get the true variation from the sun I run East, bet. secs. 23 and 26 at a Var. of 20°E.</p>	
40.00	Set temp. $\frac{1}{4}$ sec. post.	
85.50	Intersect line 21 lks. N. of post, cor. to secs. 23, 24, 25 and 26. Thence N.89°51'W., on a true line bet. secs. 23 and 26.	
40.00	Set $\frac{1}{4}$ sec. post, from which An Oak, 6 ins. diam., bears N.50°W., 25 lks.	300