

Subdivisions of T. 32 S., R. 5 W.,

CHAINS		
35.75	Top of ridge. C. SE. and NW.	+1200
46.75	Begin descent.	+1200
40.37	Set $\frac{1}{2}$ sec. post, from which A Chinquapin, 9 ins. diam. bears S.70*E., 8 lks. A Chinquapin, 10 ins. diam. bears N.30*W., 15 lks.	1000
80.75	The cor. to secs. 3, 4, 9 and 10. Land Mountainous 3rd rate. Timber 3rd rate, mostly destroyed by fire.	+200
<hr/>		
N. bet. secs. 8 and 9.		
10.00	Begin ascent. Va. 19*45'E.	
40.00	Set $\frac{1}{2}$ sec. post, from which A laurel, 6 ins. diam. bears S.62*E., 28 lks. A laurel, 8 ins. diam. bears S.45*W., 32 lks.	800
65.00	Top of ridge. C. SE. and NW.	1500
80.00	Set post cor. to secs. 4, 5, 8 and 9, from which A fir, 36 ins. diam. bears N.52*E., 106 lks. A cedar, 6 ins. diam. bears S.70*E., 50 lks. A fir, 36 ins. diam. bears S.65*W., 33 lks. A laurel, 8 ins. diam. bears N.45*W., 85 links. S. part 2nd rate, N. part 3rd rate. Timber S. part good, N. part poor. Underbrush thick. Fir, Pine, Cedar, Yew, Laurel and a few other Species. October 19, 1871.	
<hr/>		
East, on a random line bet. secs. 4 and 9.		