

## County Surveyor's Record, Douglas County, Oregon

## Subdivisional Lines of T. 32 S., R. 5 W.,

CHAINS	
	dense undergrowth of young firs and hazel.
28.00	A spring branch, 1 lk. wide. C. SE.; descent becomes more gradual.
35.00	Ft. of descent; enter bottom, heavily timbered; 250 ft. below top of spur.
37.00	A Trail, bears N. and S.
37.75	A creek, 15 lks. wide. C. S.20*W.
44.00	Begin ascent of W. mountain slope.
44.45	Set a yew post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S. 7 on N. and 18 on S. face from which <p style="margin-left: 40px;">A Fir, 40 ins. diam. bears N.79*E., 55 lks.  Marked <math>\frac{1}{4}</math> S. 7 B.T.  A Fir, 10 ins. diam. bears S.8<math>\frac{1}{2}</math>*E., 30 lks.  Marked <math>\frac{1}{4}</math> S. 18 B. T.</p>
	Continue ascent of a steep and rocky W. mountain slope, Covered heavily with large firs and cedar.
84.45	The cor. of secs. 7, 8, 17 and 18; 350 ft. above $\frac{1}{4}$ sec. cor. Land mountainous. Soil, loam, gravelly or rocky; 3rd and 4th rate. Timber, fir, cedar, sugarpine, chincopin, laurel. Undergrowth, hazel, small firs. Mountainous or heavily timbered Land 84.45 chs.
	N.0*1'W., bet. secs. 7 and 8. Descend W. mountain slope, covered heavily with timber.
6.50	Very steep descent of N. slope.
13.50	Ft. of very steep descent, along W. slope; 150 ft. below sec. cor.
25.00	Begin ascent of SW. slope, covered densely by small firs.
30.50	Top of spur, bears NW. and SE.; 100 ft. above ft. of ascent; begin descent of N. slope, covered heavily with fir, cedar and pine timber.