

66  
County Surveyor's Record, Douglas County, Oregon

Subdivisional Lines of T. 32 S., R. 5 W.

CHAINS

Mountainous or heavily timbered land 76.72 chs.,  
connecting line 0.74 chs.

July 27, 1901.

General Description

The southern part of the township now surveyed is principally mountainous; the soil ranges from rocks on top and sides of the mountain to good loam in the bottoms of a few creeks. Every where there is plenty of good, large fir and sugar pine and cedar timber. Water is plenty in streams and springs throughout the year. The NW. part is not as good. There are no settlers on any place, in fact, there is probably only 3 locations, and poor ones at that for to induce people to take homestead. Gold mining is carried on to some extent but the yield is not sufficient to justify any great expenses.

Retracement of Subdivisional Lines of  
T 32 S., R. 5 W.,  
as surveyed by Oscar F. Thiel, Deputy Surveyor,  
under special instructions, dated Sept. 12, 1901,  
In connection with his Contract No. 729,  
dated , Dec. 24, 1900.

I begin at cor. of secs. 25, 26, 35 and 36,  
heretofore described.

North, bet. Secs. 25 and 26.

Ascend a steep, rocky SW. slope of mountain,

covered with a dense undergrowth of small live oak.

6.50 Top of spur, bears E. and W., 150 ft. above Sec. cor.;  
enter big fir timber, bears E. and W.; begin  
sharp descent.

18.90 A creek, 15 lks. wide. C. W., 200 ft. below top of  
spur, begin ascent.