

County Surveyor's Record, Douglas County, Oregon

Retracement of Subdivisional Lines of T. 32 S., R. 5 W.

CHAINS	bears E. and W.
57.70	Irrigation ditch, 2 lks. wide, C. NW.
71.70	Leave slashing; enter bottom, covered densely with Vine Maple and Ash.
78.71	The cor. of Secs. 22, 23, 26 and 27 bears W., 130 lks. Intersect E. and W. line 130 lks., E. of cor. of secs. 22, 23, 26 and 27, making true bearing of line N.5°38'W., which is a Yew post, 4 ins. sq., 3 ft. above ground, set by the Co. Surveyor and witnessed as described by the surveyor general. Land, rolling and level. Soil, loamy and gravelly, 1st and 2nd rate. Timber, Fir, Pine, Cedar, Laurel. Undergrowth, Hazel, small Firs, Pines.
	Return to cor. of Secs. 26, 27, 34 and 35. Thence I run West, bet. secs. 27 and 34. Ascend E. mountain slope, covered with a dense undergrowth, bears N. and S.
15.40	Top of spur, bears N. and S.; 200 ft. above sec. cor.; leave undergrowth, enter large Fir timber of heavy growth; bears N. and S.
39.89	The $\frac{1}{2}$ Sec. cor. bears S., 14 lks., 150 ft. below top of spur. The true bearing of this line, N.89°48'E. Land, mountainous; soil, gravelly, 3rd rate. Timber, Fir, Pine, Cedar, Laurel, Dogwood. Undergrowth, Hazel, Arrowwood, small Firs.
	August 21, 1901.
	At the cor. of Secs. 28, 29, 32 and 33, herebefore described. Thence I run North, bet. Secs. 28 and 29. Descend a N. hillside, heavily timbered.
6.80	Ft. of descent, 60 ft. below Sec. cor.; go along E. slope, covered with large Firs and Cedars.
23.50	A stream, 2 lks. wide, C. E.; begin ascent.