

County Surveyor's Record, Douglas County, Oregon

Seventh Standard Parallel S., R. 6 W., on North
Boundary of T. 33 S., R. 6 W.

CHAINS		
40.00	Set $\frac{1}{4}$ sec. post on N. slope, from which A Fir, 20 ins. diam., bears S.21*E., 40 lks. dist. A Fir, 16 ins. diam., bears S.62*W., 122 lks. dist. Va. 18*30'E	+40
45.50	Branch, 3 lks. wide, course N.	-10
46.95	A Fir, 12 ins. diam.	+10
80.00	Set post, cor. to secs. 2 and 3, T. 33 S., R. 6 W., from which A Laurel, 4 ins. diam., bears S.1*W., 40 lks. dist. A Fir, 24 ins. diam., bears S.48*E., 92 lks. dist. This mile runs over a broken surface, sloping to the N. to Cow Creek valley and has a heavy growth of Fir and Sugar Pine timber. Undergrowth, Fir, Vine Maple, Hazel and Chinquapin, very thick. Soil, 2nd. rate.	+40
West, on the North Boundary of sec. 3. Va. 19*00'E		
2.00	Begin descent.	
5.67	Red Fir, 16 ins. diam.	-30
25.50	Enter Cow Creek bottom, course S.20*W., and N.20*E.	-75
32.54	Red Fir, 16 ins. diam.	Lev.
40.00	Set post, $\frac{1}{4}$ sec. from which A Red Fir, 12 ins. diam., bears S.55*W., 32 lks. dist. A Red Fir, 15 ins. diam., bears S.40*E., 28 lks. dist.	Lev.
41.75	A White Fir, 33 ins. diam.	Lev.
46.50	Left bank of Cow Creek, course S.50*W., from N.40*E., 1 ch. wide, 3 ft. deep. Bank 5 ft. high. Over creek to right bank, N.45*E., 2 chs. for base. Object on left bank bears S.45*E., distance on line 282 lks.	
49.32	Right bank.	