

Seventh Standard Parallel S., R. 6 W., on North
Boundary of T. 33 S., R 6 W.

CHAINS		
	of mountain.	
	Laurel, Cedar, Pine and Fir, timber, with Hazel, Arrow Wood, Salal, Chinquapin and Vine Maple undergrowth.	
	Soil on the mountain decayed granite, 3rd. rate and unfit for settlement.	
<hr/>		
	West, on North Boundary of Sec. 6.	
		Va. 19°E
4.11	A Fir, 16 ins. diam.	+25
11.50	Summit of mountain, course N.	+500
30.00	Begin steep descent.	-390
40.00	Set $\frac{1}{2}$ sec. post on steep descent W., from which	-300
	A Laurel, 3 ins. diam., bears S.33°E., 97 lks. dist.	
	A Fir, 15 ins. diam., bears S.59°W., 117 lks. dist.	
47.40	Perpendicular ledge, 30 ft. high, course NW. and SE.	-125
52.40	Branch in deep ravine, course NW.	-150
55.20	A Fir, 18 ins diam., (on spur, course N).	
72.00	Enter Cow Creek bottom, NE. and SW.	-100
80.00	Set post, cor. to T. 33 S., Rs. 6 and 7 W., on left bank of Cow Creek, from which	
	An Alder, 18 ins. diam., bears S.62°E., 22 lks. dist.	
	An Ash, 10 ins. diam., bears S.70°W., 35 lks. dist.	
	A Fir, 15 ins. diam., bears S.39°W., 67 lks. dist.	
	No trees taken N. of Standard line, except the last 8 chs. on Cow Creek bottom. This mile runs over high rocky mountain, unfit for settlement.	
	Fir, Laurel, Live Oak, Chinquapin and Yew timber, with thick undergrowth, Laurel, Hazel, Arrow Wood, Vine Maple.	
	Cow Creek runs nearly W. from this cor., for about 2 miles, thence Northwesterly.	