

## County Surveyor's Record, Douglas County, Oregon

Rechaining of Seventh Parallel S., R. 6 W., on  
North Boundary of T. 33 S., R. 6 W. Same Deputies and Contract.

CHAINS		
	West, on the South Boundary of Sec. 36	
		Va. 18°30'E
1.80	Branch, 2 lks. wide, course N.20°W.	-20
7.50	A ridge, course N.20°W.	+75
11.68	A Red Fir, 36 ins. diam.	
15.50	Riverlet from N. slope of mountain, 1 lk. wide,	-30
17.50	Top of ridge, N. slope of mountain.	+40
22.50	Begin descent.	lev.
32.50	Branch, 5 lks. wide, course N.5°E.	-120
37.00	Standard $\frac{1}{2}$ sec. cor.	
40.00	Set $\frac{1}{2}$ sec. post, from which	
	A Fir, 5 ins. diam., bears N.5°W., 66 lks. dist.	
	A Laurel, 3 ins. diam., bears N.75°E., 38 lks. dist.	
59.25	Top of ridge, NE. and SW. Ridge continues around to SE. thence NE. to line.	+600
74.50	Along N. slope of mountain South of Cow Creek.	-150
	Begin rapid descent to Cow Creek bottom.	
77.00	To Standard sec. cor.	
80.00	Set post cor. to secs. 35 and 36, T. 32 S., R. 6 W.,	-420
	from which	
	A Fir, 18 ins. diam., bears N.40°W., 14 lks. dist.	
	A Fir, 16 ins. diam., bears N.61°E., 43 lks. dist.	
	This mile runs along the N. slope of mountain South of Cow Creek. Surface very broken and unfit for cultivation.	
	Cow Creek is about $\frac{3}{4}$ mile N. and general course N.80°W.	
	Timber, Fir, with Hazel and Grease Wood undergrowth very thick.	
	and 3rd. rate	
	Soil, 2nd. rate. Some quartz and slate rock, indicating a gold region.	
	West, on South Boundary of Sec. 35.	
		Va. 18°35'E
14.10	A branch, 2 lks. wide, course S.70°W.	-130