

East Boundary of T. 32 S., R 7 W., as surveyed
by W. H. Byars, Deputy Surveyor, under Contract
No. 420, dated Sept. 16, 1881.

CHAINS

A Fir, 6 ins. diam., bears N. 48*W., 9 lks. dist.

Marked T 32 S R 7 W S 1 B T.

Land, high, mountainous.

Soil, rocky, 4th. rate.

Timber, chiefly Fir, Pine and Cedar. Underbrush same and
Laurel.

North, between Secs. 1 and 6.

Va. 19*E

- 1.40 Creek, 4 lks. wide, course W.
- 3.23 Old cor. Destroyed same and witness trees.
- 16.50 Spring, course W.
- 30.70 Creek, 2 lks. wide, course W. Ascend.
- 40.00 Set a Laurel post 4 ft. long, 4 ins. sq., 18 ins. in the
ground. Marked $\frac{1}{4}$ S. on W side for the $\frac{1}{4}$ sec. cor., from
which
- A Laurel, 16 ins. diam., bears S.80*E., 17 lks. dist.
Marked $\frac{1}{4}$ S B T.
- A Pine, 4 ins. diam., bears West 32 lks. dist
Marked $\frac{1}{4}$ S B T.
- 43.70 Old $\frac{1}{4}$ sec. cor. Destroyed same and witness trees.
- 55.50 Top of spur, course W. Steep descent.
- 57.20 Canyon, course W. Steep ascent.
- 70.00 Top of ridge, course NW. descend.
- 80.44 To township cor.

Subdivisions of T. 32 S., R. 6 W.
Same Deputy and Contract.

A portion of the T. being already subdivided, I began
at the cor. to secs. 23, 24, 25 and 26. Cor. post
destroyed, re-established same as per notes furnished,
viz: Set an Oak post 4 ft. long, 20 ins. in the
ground, 4 ins. sq. Marked T 32 S R 6 W S 24 on NE.
side. S 25 on SE. S 26 on SW. and S 23 on NW. side.