

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 32 S., R. 6 W.

CHAINS

42.00 Enter bottom.

57.25 Creek, 30 lks. wide, course S.

59.50 Wagon road, course N. and S.

62.00 Begin ascent.

78.00 Top of ridge, course N.

79.80 Intersect N. and S. line, 62 lks. N. of cor., to secs. 13, 14, 23 and 24.

Thence, N.89*33'W., on true line between secs. 14 and 23.

Lat. 43*42'N.

Va. 19*E

39.90 Set a Fir, post 3 ft. long, 3 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S. on N. face, from which

A Fir, 10 ins. diam., bears S.1*W., 24 lks. dist., marked $\frac{1}{4}$ S B T.

A Fir, 8 ins. diam., bears N.8*W., 55 lks. dist., marked $\frac{1}{4}$ S B T.

79.80 The cor. to secs. 14, 15, 22 and 23.

Land, mountainous.

Soil, mostly 3rd. rate. In valley along creek 1st. rate.

Timber, Fir, Cedar, Pine, Laurel Yew and Alder.

Undergrowth same.

Mr. Hansbrough has a dwelling house and saw mill near the center of sec. 23. Value unknown.

North, between secs. 14 and 15.

Va. 19*30'E

21.00 Top of ridge, course NW.

39.50 A spring, course East.

40.00 Set a Fir, post 3 ft. long, 3 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S. on W. face, from which

A Fir, 15 ins. diam., bears N.32*E., 12 lks. dist., marked $\frac{1}{4}$ S B T.

A Fir, 18 ins. diam., bears N.5*W., 15 lks. dist., marked $\frac{1}{4}$ S B T.