

Subdivisions of T 32 S., R. 6 W.

CHAINS

40.00 Set temp $\frac{1}{4}$ sec. cor.

79.64 Intersect North Boundary of Township 96 lks. East of cor.

to secs. 3, 4, 33 and 34, which is a post 4 ins. sq., set firmly in the ground and marked T 31 S R 6 W S 34 on NE. T 32 S S 3 on SE. S 4 on SW., and S 33 on NW faces, with 3 notches on E and W edges, from which

A Fir, 40 ins. diam., bears N.72°E., 72 lks. dist., marked T 31 S R 6 W S 34 B T.

A Fir, 36 ins. diam., bears S.25°E., 62 lks. dist., marked T 32 S R 6 W S 3 B T.

A Fir, 30 ins. diam., bears S.4°W., 76 lks. dist., marked T 32 S R 6 W S 4 B T.

A Fir, 34 ins. diam., bears N.59°W., 73 lks. dist., marked T 31 S R 6 W S 33 B T.

Thence S.0°41'E., on true line between secs. 3 and 4.

Va. 18°30'E

39.64 Set a Cedar post 3 ins. sq., 3 ft. long, 24 ins in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on " face, from which

A Fir, 16 ins. diam., bears S.82°E., 9 lks. dist., marked $\frac{1}{4}$ S B T.

A Fir, 36 ins. diam., bears N.70°W., 25 lks. dist., marked $\frac{1}{4}$ S B T.

79.64 The cor. to secs. 3, 4, 9 and 10.

Land mountainous, 3rd. rate.

Timber, Fir, Pine, Cedar, Laurel, Chinquapin.

November 16, 1881

Beginning at the cor. to secs. 20, 21, 28 and 29, which is a post 4 ins. sq., set firmly in the ground and marked T 32 S R 6 W S 21 on NE. S 28 on SE. S 29 on SW. and S 20 on NW. faces, with 2 notches on S. and 4 notches on E edges, from which

A Laurel, 12 ins. diam., bears S.45°W., 18 lks. dist., marked T 32 S R 6 W S 29 B T.