

Subdivisions of T. 32 S., R. 6 W.

CHAINS

40.00 Set temp. $\frac{1}{4}$ sec. cor.

79.30 Intersect N. boundary of township 145 lks. East. of cor. to secs. 4, 5, 32 and 33 which is a Chinquapin post 4 ins. sq. set firmly in the ground and marked T 31 S R 6 W S 33 on NE. T 32 S S 4 on SE. S 5 on SW. and S 32 on NW. faces, with 2 notches on W and 4 notches on East edges, from which

A Laurel, 5 ins. diam., bears N.47*E., 32 lks. dist., marked T 31 S R 6 W S 33 B T.

A Chinquapin, 5 ins. diam., bears, S.65*E., 6 lks. dist., marked T 32 S R 6 W S 4 B T.

A Fir, 18 ins. diam., bears, S.34*W., 33 lks. dist., marked T 32 S R 6 W S. 5 B T.

A Chinquapin, 6 ins. diam., bears, N.35*W., 66 lks. dist., marked T 31, S.R 6 W S 32 B T.

Thence S.1*2' E., on true line between secs. 4 and 5.

Va.20*30'E

39.30 Set a Cedar post 3 ft. long, 3 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on W. face from which

A Fir, 30 ins. diam., bears, N.30*E., 26 lks. dist., marked $\frac{1}{4}$ S B T.

A Fir, 20 ins. diam., bears, N.15*W., 34 lks. dist., marked $\frac{1}{4}$ S B T.

79.30 The cor to secs. 4, 5, 8 and 9.

Land mountainous.

Soil, 3rd. rate.

Timber, Fir, Pine, Cedar, Laurel and Chinquapin.

Undergrowth same.

November 18, 1881.

The post to secs. 29, 30, 31 and 32 being destroyed I re-established same as per notes furnished. Bearing trees all standing, viz: Set a post 4 ft. long, 4 ins. sq., 24 ins. in the ground, for the cor. marked T 32 S R 6 W S 29 on NE. S 32 on SE. S 31 on SW. S 30