

Subdivisions of Tp. 32 S., R 7 W.

CHAINS

Mr. C. Anderson has settled on the SW  $\frac{1}{4}$  of Sec. 36 improvements good dwelling house, barn, and 50 acres, inclosed valued at about \$1,200.00 or \$1,500.00.

North, between Secs. 25 and 26.

Va.18\*E.

- 17.50 Top of high ridge course E and W descend
  - 35.00 Foot of hill, Begin ascent.
  - 40.00 Set A Cedar post, 4 feet long 4 ins. sq., 22 ins. in the ground, marked  $\frac{1}{4}$  S on W face, for the  $\frac{1}{4}$  Sec. Cor. from which;
    - A Fir, 40 ins. diam., bears N.88\*E., 32 lks. dist. marked  $\frac{1}{4}$  S B T.
    - A Fir, 40 ins. diam., bears N.30\*W., 52 lks. dist. marked  $\frac{1}{4}$  S B T.
  - 73.25 Top of Spur, course E descend.
  - 80.00 Set A Fir post, 4 $\frac{1}{2}$  feet long 4 ins. sq., 18 ins. in the ground, for the cor. to Secs. 23, 24, 25 and 26, marked T 32 S R 7 W S 24 on NE S 25 on SE S 26 on SW and S 23 on NW also two notches on S and one on E angles of same from which;
    - A Fir, 10 ins. diam., bears N.18\*E., 17 lks. dist. marked T 32 S R 7 W S 24 B T.
    - A Fir, 16 ins. diam., bears S.45\*E., 71 lks. dist. marked T 32 S R 7 W S 25 B T.
    - A Laurel, 12 ins. diam., bears S.50\*W., 22 lks. dist. marked T 32 S R 7 W S 26 B T.
    - A Chinquapin, 12 ins. diam., bears N.3\*W., 36 lks. dist. marked T 32 S R 7 W S 23 B T.
- Land, mountainous from 17.50 on E slope of mountain.  
 Soil, rocky 4th rate.  
 Timber, chiefly Fir, Pine, Cedar, Laurel, and Chinquapin.  
 Underbrush very dense same mountain Balm, Live Oak and "Buck" brush.