

## Subdivisions of Tp. 32 S., R 7 W.

CHAINS	
	East on Random line between Secs. 24 and 25. Va.18*E.
	Steep descent.
40.00	Set temporary $\frac{1}{4}$ Sec. Cor.
41.40	Creek 12 lks. wide course S Begin ascent.
74.00	Top of Spur course South.
80.60	Intersect E boundary of Tp. 210 lks. S of Cor. to secs. 19, 24, 25, and 30, viz., A Chinquapin post, 4 ins. sq., firmly set in the ground, marked T 32 S R 6 W S 19 on NE S 30 on SE; S 25 on SW and T 32 S R 7 W S 24 on NW faces, also two notches on S and four notches on N angles, from which; A Laurel, 6 ins. diam., bears N.85*E., 23 lks. marked T 32 S R 6 W S 19 B T. A Fir, 30 ins. diam., bears S.15*E., 28 lks. dist. marked T 32 S R 6 W S 30 B T. A Laurel, 8 ins. diam., bears S.10*W., 38 lks. marked T 32 S R 7 W S 25 B T. A Laurel, 8 ins. diam., bears N.20*W., 44 lks. marked T 32 S R 7 W S 24 B T. Thence I run S 88*30'W on a true line between Secs. 24 and 25. same Va.
40.30	Set A Yew post, 4 feet long 4 ins. diam., 18 ins. in the ground, marked $\frac{1}{4}$ S on N face, for the $\frac{1}{4}$ Sec. Cor. from which; A Fir, 30 ins. diam., bears North 6 lks. dist. marked $\frac{1}{4}$ S B T. A Cedar, 10 ins. diam., bears S.30*E., 36 lks. marked $\frac{1}{4}$ S B T.
80.60	To cor. to secs. 23, 24, 25, and 26. Land, steep mountainous. Soil, E part clay 3rd and W part rocky 4th rates. Timber, Fir, Pine, Cedar, Yew, Laurel and Live Oak. Underbrush same and Balm. October 25, 1881.