

## Subdivisions of Tp. 32 S., R 7 W.

CHAINS

Land high mountainous, broken and rocky.

Soil burned rocky 4th rate.

Timber all burned.

Undergrowth very dense chiefly Fir, Laurel, Balm, Live Oak, and "Manzanita".

Noth between Secs. 13 and 14.

Va. 18° E.

Continue descent.

17.00 Dry ravine course S Broken W slope of mountain.

40.00 Set A Fir post 4 feet long 4 ins. sq., 20 ins. in the ground for the  $\frac{1}{4}$  S cor. marked  $\frac{1}{4}$  S on W side from which:

A Fir, 10 ins. diam., bears N.7° E., 13 lks.  
dist. marked  $\frac{1}{4}$  S B T.

A Laurel, 6 ins. diam., bears S.80° W., 12 lks.  
dist. marked  $\frac{1}{4}$  S B T.

43.00 Creek 2 lks. wide course W.

68.00 Top of Ridge course NW. and SE Enter burned woods.

80.00 Set A Fir post, 4 $\frac{1}{2}$  feet long 4 ins. sq., 18 ins. in the ground for the cor. to Secs. 11, 12, 13, and 14, marked T 32 S R 7 W S 12 on NE S 13 on SE S 14 on SW and S 11 on NW faces also 4 notches on the S and one on the E Angle of same, from which:

A Cedar, 12 ins. diam., bears S.78° E., 26 lks.  
dist. marked T 32 S R 7 W S 13 B T.

A Laurel, 7 ins. diam., bears S.45° W., 20 lks.  
dist. marked T 32 S R 7 W S 14 B T.

A Fir, 48 ins. diam., bears N.82° W., 106 lks.  
dist. marked T 32 S R 7 W S 11.

No Tree convenient in Sec. 12

Land mountainous and broken.

Soil clay rocky and gravel 4th rate.

Timbers chiefly Fir, Cedar, Pine, Yew, Laurel, and Chinquapin.