

## Subdivisions of Tp. 32 S., R 7 W.

CHAINS

80.30 To Corner to Secs. 26, 27, 34, and 35.

Land mountainous and broken.

Soil rocky 4th rate.

Timber poor chiefly Live Oak, Fir, Pine, Chinquapin,  
Cedar and Laurel.

Undergrowth same. very dense. Lat. 42° 41' N

North between Secs. 26 and 27

Va. 16° E

12.00 Top of Ridge-high Point Along W Slope.

40.00 Set A Pine post, for the  $\frac{1}{4}$  Sec. Cor. 4 feet long 4 ins.  
sq., 20 ins. in the ground, marked  $\frac{1}{4}$  S from which:

A Pine, 14 ins. diam., bears N.30° E., 88 lks.

dist. marked  $\frac{1}{4}$  S B T.

A Pine, 30 ins. diam., bears S.65° W., 148 lks.

dist. marked  $\frac{1}{4}$  S B T.

53.00 Begin descent.

72.00 Creek 1 1/2 wide course NW

80.00 Set A Laurel post, 4 feet 4 ins. sq., 18 ins. in the  
ground for the  $\frac{1}{4}$  Sec. Cor. to Secs. 22, 23, 26, and 27  
marked T 32 S R 7 W S 23 on NE S 26 on SE S 27 on SW  
and S 22 on NW faces also two notches on S and E  
angles of same from which:

A Fir 36 ins. diam., bears N.33° E., 18 lks.

dist. marked T 32 S R 7 W S 23 B T.

A Fir, 14 ins. diam., bears S.40° E., 22 lks.

dist. marked T 32 S R 7 W S 26 B T.

A Sugar Pine, 36 ins. diam., bears S.35° W., 30 lks.

dist. marked T 32 S R 7 W S 27 B T.

A Fir, 30 ins., diam., bears N.40° W., 14 lks.

dist. marked T 32 S R 7 W S 22 B T.

Land mountainous 3rd rate.

Soil rocky.

Timber chiefly Fir, Pine, Cedar and Laurel.

Undergrowth same Live Oak, "Manzanita".