

Subdivisions of Tp. 32 S., R 7 W.

CHAINS

80.10 To corner to Secs. 9, 10, 15 and 16
 Land mountainous and broken.
 Soil 3rd rate.
 Timbers chiefly Fir, Pine, Cedar, Laurel Oak and Yew.
 Underbrush same.
 November 1st. 1881.

North between Secs. 9, and 10.

Va. 19° E

23.00 Creek 2 lks wide course SE
 30.00 Begin steep ascent.
 40.00 Set A Fir post, 4 feet long 4 ins. sq., 22 ins. in the
 ground for the $\frac{1}{4}$ Sec. Cor. marked $\frac{1}{4}$ S from which:
 on W
 A Pine, 24 ins. diam., bears N. 10° E., 85 lks.
 marked $\frac{1}{4}$ S. B T.
 A Pine 24 ins. diam., bears S. 5° W., 385 lks.
 marked $\frac{1}{4}$ S B T.
 58.00 Top of Ridge course E and W Begin descent.
 80.00 Set A Fir post, 4 feet long 4 ins. in diam., 20 ins. in
 the ground for the cor. to secs. 3, 4, 9 and 10 marked
 T 32 S R 7 W 3 on NE S 10 on SE S 9 on SW and S 4 on
 NW angles, with 5 nothces on S and 3 on E of same,
 from which:
 A Fir, 16 ins. diam., bears N. 32° E., 25 lks.
 marked T 32 S R 7 W S 3 B T.
 A Fir, 16 ins. diam., bears S. 70° E., 20 lks.
 marked T 32 S R 7 W S 10 B T
 A Fir, 20 ins. diam., bears S. 54° W., 20 lks.
 marked T 32 S R 7 W S 9 B T.
 A Laurel, 10 ins. diam., bears N. 34° W., 26 lks.
 marked T 32 S R 7 W S 4 B T.

Land mountainous.
 Broken Soil 3 rd rate.
 Timber chiefly Fir, Pine and Cedar.
 Underbrush same. Oak, Laurel and "Manzanita". and etc.