

Subdivisions of Tp. 32 S., R 7 W.

CHAINS

- 59.00 Creek. 2 lks. wide course NW
- 80.16 Intersect E boundary of Sec. 26 lks. N of Cor. to Secs. 21, 22, 27 and 28
- Thence I run
- N.89*49'W on true line between Secs. 21 and 28
- Va.20*E
- 40.08 Set A Laurel post, 4 feet long 4 ins. sq., 20 ins. in the ground, marked $\frac{1}{4}$ S for the $\frac{1}{4}$ Sec. Cor. from which;
- A Pine, 20 ins. diam., bears S.38*W., 22 lks. marked $\frac{1}{4}$ S B T.
- A Pine, 24 ins. diam., bears N.45*W., 17 lks. marked $\frac{1}{4}$ S B T.
- 80.16 To Sec. Cor. to Secs. 20, 21, 28 and 29
- Land, mountainous.
- Soil, 3rd rate.
- Timber, chiefly Pine, Fir, Cedar, Laurel, Yew and Oak.
- Undergrowth, same.
- November 3rd 1881.
-
- North between Secs. 20 and 21
- Va.19*E
- 40.00 Set A Pine, post 4 feet long 4 ins. sq., 24 ins. in the ground, for the $\frac{1}{4}$ Sec. Cor. marked $\frac{1}{4}$ S on W side, from which;
- A Pine, 10 ins. diam., bears S.80*E., 48 lks. dist. marked $\frac{1}{4}$ S B T.
- A Pine, 9 ins. diam., bears S.78*W., 78 lks. dist. marked $\frac{1}{4}$ S B T.
- 80.00 Set A Fir post, 4 feet long 4 ins. sq., 24 ins. in the ground, marked T 32 S R 7 W S 16 on NE S 21 on SE S 20 on SW and S 17 on NW faces, also 3 notches on S and 4 notches on E angle of same, from which;
- A Live Oak, 8 ins. diam., bears N.10*E., 31 lks. marked T 32 S R 7 W S 16 B T.