

Subdivisions of Tp. 32 S., R 7 W

CHAINS

North on Randon line between Secs. 4 and 5

Va. 19°E

35.50 Top of Ridge, and Trail course E and W Steep descend.

40.00 Set temporary  $\frac{1}{2}$  Sec. Cor. along steep hillside W

53.00 Spur course NW Descend

81.66 Intersect N boundary of Township 87 lks. East of Cor. to  
Secs. 4 and 5 32 and 33 Viz:

A Chinquapin post, 4 ins. sq., firmly set in ground  
marked T 31 S R 7 W S 33 on NE T 32 S S 4 on SE  
S 5 on S W and S 32 on NW also 4 notches on E and  
2 notches on W Angles, from which:

A Fir, 14 ins. diam., bears N.54°E., 17 lks.  
marked T 31 S R 7 W S 33 B T.

A Fir, 26 ins. diam., bears S.36°E., 18 lks.  
marked T 32 S R 7 W S 4 B T.

A Fir, 16 ins. diam., bears S.12°W., 60 lks.  
T 32 S R 7 W S 5 B T.

A Laurel, 8 ins. diam., bears N.50°W., 9 lks.  
marked T 31 S R 7 W S 32 B T.

Thence I run

South 0°37'E on true line between Secs. 4 and 5

Va. 18°E

41.66 Set A Cedar post, 4 feet long 4 ins. sq., 18 ins. in  
the ground  $\frac{1}{2}$  S on W side for the  $\frac{1}{2}$  Sec. Cor.

from which:

A Fir, 15 ins. diam., bears N.40°E., 24 lks.  
marked  $\frac{1}{2}$  S B T.

A Fir, 18 ins. diam., bears S.65°W., 22 lks.  
dist. marked  $\frac{1}{2}$  S B T.

81.66 To the corner to Secs. 4, 5, 8 and 9.

Land, mountainous.

Soil, 3rd rate.

Timber, good chiefly Fir, Pine, Cedar and Laurel.

Underbrush same.

November 5th, 1881.