

## Subdivisions of Tp. 32 S., R 7 W.

## CHAINS

West on Random line between Secs. 30 and 31

Va. 18°15'E

- 5.00 Creek, 2 lks wide course NW
- 7.50 Creek, 1 lk wide course N Begin Ascent
- 28.00 Top of Spur course N Begin Descent
- 40.00 Set temporary  $\frac{1}{4}$  Sec. Cor.
- 58.00 Creek, 5 lks wide course N
- 80.60 Intersect W boundary of Township 31 lks S of corner to  
Secs. 25, 30, 31 and 36 Viz;
- A Fir Tree, 28 ins. diam., marked T 32 S R 7 W S 30 on  
NE S 31 on SE S 36 on SW and T 32 S R 8 W S 25 on  
NW side also 1 notch on South and 5 on N Angles  
of same, from which;
- A Fir, 18 ins. diam., bears N.68°E., 70 lks.  
marked T 32 S R 7 W S 30 B T
- A Fir, 20 ins. diam., bears S.70°E., 74 lks.  
marked T 32 S R 7 W S 31 B T.
- A Fir, 18 ins. diam., bears S.10°W., 72 lks..  
marked T 32 S R 8 W S 36 B T.
- A Fir, 10 ins. diam., bears N.82°W., 100 lks.  
marked T 32 S R 8 W S 25 B T.
- Thence I run  
S 89°47'E on a true line between Secs. 30 and 31  
Va. 18°E
- 40.60 Marked A Laurel, 4 ins. diam., with blaze and  $\frac{1}{4}$  S on N  
side for the  $\frac{1}{4}$  Sec. Cor. from which:
- A Laurel, 12 ins. diam., bears S.65°W., 39 lks.  
marked  $\frac{1}{4}$  S B T.
- A Laurel, 10 ins. diam., bears N.68°W., 20 lks.  
marked  $\frac{1}{4}$  S B T.
- 80.60 To Cor. To Secs. 29, 30, 31 and 32.
- Land, mountainous broken.
- Soil, rocky 3rd rate.
- Timber, good chiefly Fir, Pine, Cedar and Laurel.
- Underbrush, same Balm, Live Oak and "Manzanita".