

County Surveyor's Record, Douglas County, Oregon

West Boundary of T. 32 S., R. 8 W.

CHAINS	<p>Timber, densely covered with Fir, Pine, Laurel and Cedar.</p> <p>Undergrowth, thick, of Laurel, Fir, Balm, Live Oak and Chinquapin.</p>
<p>North, between Secs. 1 and ⁶5.</p> <p style="text-align: right;">Va. 19°45'E.</p>	
0.50	<p>A Creek, 1 lk. wide, course West. Along steep West slope of mountain.</p>
36.00	<p>A Creek, 1 lk. wide, course West.</p>
40.00	<p>Set a stone 14x12x10 ins., 10 ins. in the ground for the $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on West side, and from which</p> <p style="padding-left: 40px;">A Live Oak, 5 ins. diam., bears N.28°E., 21 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A Fir, 40 ins. diam., bears S.52°W., 11 lks. dist., marked $\frac{1}{4}$ S B T.</p>
44.60	<p>A Creek, 8 lks. wide, course N.20°E.</p> <p>Thence descend along East slope.</p>
68.00	<p>West fork, 100 lks. wide, course East, ascend.</p>
82.50	<p>Intersect South bdy. of T 31 S R 8 W. at a point 15 chs. and 60 lks. East of the established SW cor. of said Tp. at which point I set a stone 18x12x12 ins., 12 ins. in the ground for the closing cor. to Tp. 32 S R 8 and 9 W., marked CC with 6 notches on the SE and W edges, from which</p> <p style="padding-left: 40px;">A Fir, 12 ins. diam., bears S.10°E., 66 lks. dist., marked CC T 32 S R 8 W S 6 B T.</p> <p style="padding-left: 40px;">A Fir, 24 ins. diam., bears S.10°W., 70 lks. dist., marked CC T 32 S R 9 W S 1 B T.</p> <p style="padding-left: 40px;">A Fir, 60 ins. diam., bears N.14°W., 29 lks. dist., marked CC T 31 S R 9 W S 31 B T.</p> <p>Land, mountainous and broken.</p> <p>Soil, 3rd rate.</p> <p>Forest, densely covered with Fir, Cedar, Pine and Laurel.</p> <p>Undergrowth, thick with same kind as timber, with Rhododendron.</p>
<p>June 15, 1883.</p>	