

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T 32 S., R. 8 W.

CHAINS

ground for the cor. to sect. 23, 24, 25, and 26.
 Marked T 32 S R 8 W S 24 on NE. S 25 on SE. S 26 on SW and S 23 on NW faces of same also 2 notches on the S and 1 on the E angles, and from which
 A Fir, 40 ins. diam., bears N.50°E., 30 lks. dist.
 Marked T 32 S R 8 W S 24 B T.
 A Fir, 40 ins. diam., bears S.30°E., 32 lks. dist.
 Marked T 32 S R 8 W S 25 B T.
 A Live Oak, 6 ins. diam., bears S.18°W., 24 lks. dist.
 Marked T 32 S R 8 W S 26 B T.
 A Maple, 6 ins.diam., bears N.45°W., 92 lks. dist.
 Marked T 32 S R 8 W S 23 B T.
 Land, mountainous and broken.
 Soil, rocky and clay, 3rd rate.
 Timber, chiefly Fir, Pine, Laurel, and Cedar.
 Undergrowth, thick and densely covered of Laurel, Live Oak, Balm, Hazel, and Yew.

East, on Random line between Secs. 24 and 25.
 Va. 19°45'E.

- 21.00 Steep rocky ascent.
- 26.10 Top of spur, course NW. Steep descent.
- 29.75 A creek, 1 lk. wide, course North.
- 35.00 A creek, 1 lk. wide, course North. Ascent.
- 40.00 Top of Spur, course North.
- 51.00 Set temp. 1/2 sec. cor.
- 80.50 Top of ridge, course North. Gradual descent.
- Intersect East bdy. of tp., 35 lks. North of cor. to secs. 19, 24, 25, and 30, which is a Fir post 4 ins. sq. firmly set in the ground and marked.
 T 32 S R 7 W S 19 on NE; S 30 on SE R 8 W S 25 on SW and S 24 on NW faces with 4 notches on N and 2 2 notches on S angles of same, and from which