

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 32 S., R. 8 W.

CHAINS

80.44

The cor. to secs. 15, 16, 21, and 22.

Land, mountainous.

Soil, rocky, 3rd rate.

Timber, chiefly of Fir, Pine, and Laurel.

Undergrowth, Fir, Laurel, Balm, and Live Oak.

North, between secs. 15 and 16.

Va. 19°45'E.

13.00

Top of spur, course SW. Descend.

40.00

Set a Laurel post 4 ins. sq., 3 ft. long, 20 ins. in the ground marked  $\frac{1}{4}$  S on W side for the  $\frac{1}{4}$  sec. cor., from which

A Fir, 6 ins. diam., bears N.18°E., 10 lks. dist.

Marked  $\frac{1}{4}$  S B T.

A Fir, 8 ins. diam., bears S.14°W., 20 lks. dist.

Marked  $\frac{1}{4}$  S B T.

47.20

A creek, 75 lks. wide, course NE. Steep ascent along steep East slope.

80.00

Set a stone 14x12x12 marked with 4 notches on the S and 3 notches on the E, for the cor. to secs. 9, 10, 15, and 16, from which

A Laurel, 10 ins. diam., bears N.35°E., 55 lks. dist.

Marked T 32 S R 8 W S 10 B T.

A Laurel, 6 ins. diam., bears S.62°E., 68 lks. dist.

Marked T 32 S R 8 W S 15 B T.

A Fir, 24 ins. diam., bears S.28°W., 52 lks. dist.

Marked T 32 S R 8 W S 16 B T.

A Laurel, 6 ins. diam., bears N.53°W., 50 lks. dist.

Marked T 32 S R 8 W S 9 B T.

Land, mountainous, broken.

Soil, rocky, 3rd and 4th rate.

Timber, Fir, Pine, Laurel, and Cedar.

Undergrowth, thick, Fir, Laurel, Balm, Live Oak, and

Vine Maple.

June 27, 1883.