

Resurvey East Bdy., T. 32 S., R. 9 W.

CHAINS

- 18.70 Top of spur, slopes NE.; descend.
- 28.25 Creek, 15 lks. wide, course W.; ascend.
- 37.67 Intersect the point for old $\frac{1}{4}$ sec. cor., located by reference to the bearing trees as described by the surveyor general. The west bearing tree is now a burned stump and all traces of the cor. post have disappeared. I change this cor. to refer to sec. 30 only and perpetuate it as follows: at exact cor. point
- Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ cor. of sec. 30, T. 32 S., R. 8 W. only, with brass cap marked
- $\frac{1}{4}$
 S30
 1917
- from which
- A Fir, 30 ins. diam., bears N.43°E., 67 lks. dist.
marked $\frac{1}{4}$ S 30 B T (New B.T.)
- A Fir, 40 ins. diam., bears S.80°E., 19 lks. dist.
marked $\frac{1}{4}$ S 30 B T (Old B.T.)
- Thence
- N.0°25'W., continuing my measurements
- 40.00 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ cor. of sec. 25 only, with brass cap marked
- $\frac{1}{4}$
 S25
 1917
- from which
- A Fir, 36 ins. diam., bears S.32°W., 102 lks. dist.
marked $\frac{1}{4}$ S 25 B T.
- A Chinquapin, 8 ins. diam., bears N.18°W., 56 lks. dist.,
marked $\frac{1}{4}$ S 25 B T.
- 42.60 Dry ravine, course SW.
- 57.60 Top of ridge, bears E. and W.; descend rocky NE. slope.
Trail, West Fork, to Rogue River, bears E. and W.
- 69.50 Creek, 3 lks. wide, course E.; ~~ascend~~ ascend SE. slope.
- 76.21 Intersect the point for old cor. of secs. 19, 24, 25 and