

County Surveyor's Record, Douglas County, Oregon

Resurvey of East Bdy., T. 32 S., R. 9 W.

CHAINS

Set an iron post, 3 ft. long, 3 ins. diam., 24 ins. in the ground, for closing cor. of Tp. 32 S., Rs. 8 and 9 W., with brass cap marked

T31S R8W	
S31	
S1	S6
R9W	R8W
T32S	
C C	
1917	

from which

A Fir, 16 ins. diam., bears S.10°E., 66 lks.

dist., marked C C T 32 S R 8 W S 6 B T (Old B T)

A Fir, 30 ins. diam., bears S.10°W., 70 lks.

dist., marked C C T 32 S R 9 W S 1 B T (Old B T)

Land, mountainous.

Soil, stony clay loam and shale rock, 2nd, 3rd and 4th rate.

Timber, Fir, Cedar, Hemlock and Sugar Pine.

Undergrowth, Huckleberry, Rhododendron, Snowbrush, vine-maple and Hazel.

Retracement of 7th Standard Parallel S. through R.8 W.
As surveyed by Norman D. Price, U.S. Surveyor,
Under instructions dated Sept. 22, 1916.

RANDOM LINE.

From the standard cor. of Tp. 32 S., Rs. 7 and 8 W.
West on S. bdy. of Sec. 36.

38.50 Fall 65 lks. S. of the standard $\frac{1}{2}$ sec. cor.

76.92 Fall 29 lks. N. of the standard cor. of Secs. 35 and 36.

The E. half of this line is N.89°02'W., 38.51 chs.,
and the W. half is S.88°36'W., 38.43 chs.

From the standard sec. cor.

West, on S. bdy. of sec. 35.

38.64 Fall 8 lks. S. of the standard $\frac{1}{2}$ sec. cor.

76.34 Fall 102 lks. S. of the standard sec. cor.

The E. half of this line is N.89°53'W., 38.64 chs.,
and the W. half is N.88°34'W., 37.71 chs.