

County Surveyor's Record, Douglas County, Oregon

Retracement of the 7th Standard Parallel South
through R. 8 W.

CHAINS

Alongside of post,

Set a sandstone, 18 x 14 x 8 ins., 14 ins. in the ground, marked SC on N., with 6 grooves on N., E., and W. faces.

The old bearing trees being dead and no suitable bearing trees being available.

Raise a mound of stone, 2 ft. base, 1½ ft. high, N. of cor.

The closing cor. of Tp. 33 S., Rs. 7 and 8 W., heretofore described, 140 ft. below the standard Tp. cor., bears E., 6.26 chs. dist.

Thence

N.89°02'W., on a true line on S. bdy. of Sec. 36.

Ascend 15 ft. over SE. slope, through heavy standing dead timber and dense undergrowth.

1.50 Spur, slopes N., descend 1085 ft. over W. slope to the standard ¼ sec. cor.

12.80 Leave heavy standing dead timber; enter heavy green timber, bears N and S.

17.00 Head of ravine, course NW.

38.51 Find no evidence of the cor. post established for standard ¼ cor. of Sec. 36.

True point for cor. established from original bearing trees.

At the exact cor. point.

Set a granite stone, 15 x 14 x 6 ins., 10 ins. in the ground, for standard ¼ cor. of Sec. 36, marked SC ¼ on N. face.

The old bearing trees being dead, I obliterate markings on same and take new bearing trees as follows:

A Fir, 15 ins. diam., bears N.55½°E., 21 lks. dist., marked SC ¼ S 36 B T.