

County Surveyor's Record, Douglas County, Oregon

Retracement of the 7th Standard Parallel South
through R. 8 W.

CHAINS

- 38.64 Find no evidence of the cor. post established for standard $\frac{1}{2}$ cor. of Sec. 35
- True point for cor. established from original bearing trees.
- At exact cor. point.
- Set a granite stone, 15 x 8 x 6 ins., 10 ins. in the ground, for standard $\frac{1}{2}$ cor. of Sec. 35, marked SC $\frac{1}{2}$ on N face.
- The old bearing trees being in poor condition, I obliterate markings on same and take new bearing trees as follows:
- A Fir, 36 ins. diam., bears N.55*E., 90 lks. dist., marked SC $\frac{1}{2}$ S 35 B T.
- A Pine, 18 ins. diam., bears N.1*W., 64 lks. dist., marked SC $\frac{1}{2}$ S 35 B T.
- Thence N.88*34'W.
- Ascend 50 ft. over broken SE slope.
- 2.60 Spur, slopes N., descend 500 ft. over W slope.
- 27.00 Branch, 5 lks. wide, course N10*E., ascend 170 ft. over SE slope.
- 37.71 The standard cor. of Secs. 34 and 35, which is a granite stone, 12 x 10 x 4 ins. above ground, firmly set, marked as described by the surveyor general, from which the old bearing trees bear as follows:
- A Fir, 15 ins. diam., bears N.24*E., 28 lks. dist., marked SC T 32 S R 8 W S 35 B T.
- A Fir, 18 ins. diam., bears N.45*W., 63 lks. dist., marked SC T 32 S R 8 W S 34 B T.
- I obliterate markings on bearing tree referring to Sec. 2.
- Land, mountainous.
- Soil, loose, coarse, rocky loam, 3rd rate.
- Timber, Fir, Pine, Madrona, Live Oak, and Cedar.
- Undergrowth, Madrona, Live Oak, Chinquapin and Snowbrush.