

Retracement of the 7th Standard Parallel South
through R. 8 W.

CHAINS

obliterate markings on same and take new bearing trees as follows:

A Pine, 30 ins. diam., bears N.8°E., 50 lks.

dist., marked T 32 S R 8 W S 33 S C B T.

A Fir, 12 ins. diam., bears N.51½°W., 96 lks.

dist., marked T 32 S R 8 W S 32 S C B T.

Land, mountainous.

Soil, loose, coarse, rocky loam, 3rd rate.

Timber, Fir, Pine and Madrona.

Undergrowth, Chinquapin, Live Oak, Madrona and Sweet acorn.

West, on S. bdy. of Sec. 32.

Ascend 220 ft. over broken NE. slope, through heavy green timber and dense undergrowth.

9.40 Spur, slopes N., descend 445 ft. over W slope.

22.50 Ravine, course N., ascend 60 ft. over NE slope.

26.05 Spur, slopes N., descend 50 ft. over NW slope.

30.00 Ravine, course N. ascend 155 ft. over NE slope.

35.45 Spur, slopes North, thence over a N slope.

39.09 The standard ¼ cor. of Sec. 32, which is a granite stone, 10 x 8 x 4 ins. above ground, firmly set, marked and witnessed as described by the surveyor general.

The old bearing trees being in poor condition, I obliterate markings on same and take new trees as follows:

A Fir, 8 ins. diam., bears N.9°E., 5 lks.

dist., marked SC ¼ S 32 B T.

A Fir, 6 ins. diam., bears N.49°W., 18 lks.

dist., marked SC ¼ S 32 B T.

Thence S.89°50'W.

Over a N slope.