

County Surveyor's Record, Douglas County, Oregon

Retracement of 7th Standard Parallel South
through R. 8 W.

CHAINS

- 1.50 Head of ravine, course NE., ascend 380 ft. over NE slope.
- 22.00 Ridge, bears NW and SE., descend 120 ft. over SW slope.
- 39.20 Find no evidence of the cor. post established for standard cor. of Secs. 31 and 32.
True point for cor. established from original bearing trees.
At exact cor. point,
Set a diorite stone, 16 x 12 x 8 ins., 11 ins. in the ground, for standard cor. of Secs. 31 and 32, marked SC on N., with 5 grooves on E. and 1 groove on W. face.
The old bearing trees being in poor condition, I obliterate markings on same and take new bearing trees as follows:
A Fir, 32 ins. diam., bears N.47*E., 24 lks. dist., marked T 32 S R 8 W S 32 S C B T.
A Fir, 26 ins., diam., bears N.26*W., 30 lks. dist., marked T 32 S R 8 W S 31 S C B T.
Land, mountainous.
Soil, loose, coarse, gravelly loam, 3rd rate.
Timber, Fir, Pine and Madrona.
Undergrowth, Buckhorn, Snowbrush, Chinquapin, Madrona, and Manzanita.
-
- S.89*51'W., S. Bdy. of Sec. 31.
Descend 55 ft. over SW slope, through heavy green timber and dense undergrowth.
- 9.90 Head of ravine, course S., ascend 10 ft. over SE slope.
- 15.75 Ridge, bears NE and SW., thence over a broken N slope.
- 25.50 90 ft. below point at 15.75 chs., same ridge, bears SE and W., thence along top of ridge.
- 32.50 Leave ridge, bears E and SW., descend 60 ft. over NW slope.