

Retracement of the 7th Standard Parallel South
through R. 8 W.

CHAINS

- 39.91 The standard $\frac{1}{4}$ cor. of Sec. 31, which is a granite stone, 12 x 8 x 4 ins. above ground, firmly set, marked and witnessed as described by the surveyor general.
- Obliterate markings on bearing tree referring to Sec. S of line and take new bearing tree as follows:
- A Fir, 15 ins. diam., bears N.41*E., 59 lks. dist., marked SC $\frac{1}{4}$ S 31 B T.
- Thence N.89*58'W.
- Descend 30 ft. over NW slope.
- 4.00 Head of ravine, course N., ascend 80 ft. over NE slope.
- 7.75 Ridge, bears NW and SE,, ascend 240 ft. over SE slope to spur.
- 8.00 Leave heavy timber, bears N and S., continue through heavy standing dead timber.
- 28.70 Spur, slopes SW., enter heavy green timber, bears NE and SW.
- Descend 270 ft. over NW slope.
- 39.91 The standard cor. of Tp. 32 S., Rs. 8 and 9 W., which is a Fir post, 4 ins. sq., 30 ins. above ground, with an iron post, 3 ins. diam., 12 ins. above ground alongside, both firmly set and marked and witnessed as described by the surveyor general.
- Land, mountainous.
- Soil, loose, coarse, gravelly loam, 3rd rate.
- Timber, Fir, Pine and Madrona.
- Undergrowth, Buckhorn, Snowbrush, Chinquapin and Live Oak.