

Exteriors of T. 32 S., R. 10 W.

CHAINS

A Pine, 30 ins. in diam., bears N.27*W., 88 lks. dist.,
marked T 31 S R 10 W S 36 B T.

Land, high mountainous, rocky and broken.

Soil, 4th rate.

Densely covered with forest of timber on N. and E. side
of mountain. Scattering on S. and W. side.

Timber, chiefly Pine and Fir.

Thick undergrowth, on S. and W. sides of mountain, chiefly
Live-oak, and Balm. Rhododendron, Fir, and Yew on N.
and E. sides, only scattering.

June 10th, 1883.

Resurvey of East Bdy. of T. 32 S, R. 10 W.
as surveyed by George S. Pershin, Deputy Surveyor,
under Contract No. 728, dated Dec. 20, 1900.

80.00

North, bet. Secs. 24 and 19 *****

To a point 1.36 chs. N. and 2.12 chs., East of old cor.
which I totally obliterate.

Set a stone 15x10x8 ins., 10 ins. in the ground for cor.
of Secs. 13, 24, 18 and 19, marked with 3 notches on N.
and S. edges from which

A Fir, 28 ins. in diam., bears N.25*E., 90 lks. dist.,
marked T 32 S R 9 W S 18 B T.

A Fir, 28 ins. in diam., bears S.20*E., 93 lks. dist.,
marked T 32 S R 9 W S 19 B T.

A Fir, 18 ins. in diam., bears S.72*W., 51 lks. dist.,
marked T 32 S R 10 W S 24 B T.

A Fir, 60 ins. in diam., bears N.40*W., 42 lks. dist.,
marked T 32 S R 10 W S 13 B T.

This cor. is about 300 ft. below top of ridge.

Land, mountainous.

Soil, 3rd rate.