

County Surveyor's Record, Douglas County, Oregon

8

Resurvey of East Bdy. of T. 32 S., R. 10 W.

CHAINS

10 W. which is a stone 8x5x4 ins. above the ground marked and witnessed as described by the surveyor General.

Land, mountainous.

Soil, 3rd rate.

Timber, irregular partly heavy and partly scattering.

Fir, Pine, Cedar, Hemlock, Yew, Chinquapin, Madrona, and Live Oak.

Undergrowth, young Chinquapin, Manzanita, Salal and Laurel.

Mountainous, heavily timbered or of dense undergrowth.

78.45 chs.

July 17, 1901.

Resurvey of Portion of West Bdy. of T. 32 S., R. 9 W. as surveyed by Fred Mensch and Gerald A. Sorrels, Deputy Surveyors under Special Instructions dated Dec. 22, 1916.

N.1*10*W., resurveying W. bdy. of sec. 19.*****

75.27 Intersect the old cor. of secs. 13, 18, 19 and 24, which is a basalt stone, 15x10x8 ins., loosely set, marked and witnessed as described by the surveyor general. I change this cor. to refer to secs. 13 and 24 only and perpetuate it as follows: alongside the old cor.

Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for cor. of secs. 13 and 24, T. 32 S., R. 10 W. only, with brass cap marked

T32S
S13
S24
R10W
1917

from which

A Fir, 20 ins. diam., bears S.80*W., 50 lks. dist., marked T 32 S R 10 W S 24 B T (Old B.T.)

A Fir, 60 ins. diam., bears N.38*W., 40 lks. dist., marked T 32 S R 10 W S 13 B T (Old B.T.)

Thence

N.0*22*W., continuing my measurements