

9

Resurvey of Portion of West Bdy. of T. 32 S., R. 9 W.

CHAINS

50.02 (80.00 chs. latitude)

Set an iron post, 3 ft. long, 2 ins. in diam., 24 ins. in the ground, for cor. of secs. 18 and 19, with brass cap marked

T32S
S18
S19
R9W
1917

from which

A Fir, 18 ins. diam., bears N.70*E., 46 lks. dist., marked T 32 S R 9 W S 18 B T.

A Fir, 30 ins. diam., bears S.42*E., 13 lks. dist., marked T 32 S R 9 W S 19 B T.

Land, mountainous.

Soil, gravelly clay loam, 2nd and 3rd rate.

Timber, fir, cedar, sugar pine and laurel.

Undergrowth, tan oak, rhododendron, live oak and young fir.

N.0*22'W., resurveying W.bdy. of sec. 18.

Across top of spur, through heavy timber and dense undergrowth.

0.10 Top of spur, slopes SW.; descend.

7.90 Ravine, course NW.

12.40 Rocky ravine, course W.; ascend.

16.00 Ravine, course SW.

18.00 Leave timber; enter dense live oak thickets, bears E. and W.

29.00 Top of ridge, bears E. and W.; descend steep slope.

Enter timber, bears E. and W.

32.96 Intersect the old $\frac{1}{4}$ sec. cor., which is a basalt stone, 15x12x10 ins., loosely set, marked and witnessed as described by the surveyor general. I change this cor. to refer to sec. 13 only and perpetuate it as follows: alongside the old cor.