

County Surveyor's Record, Douglas County, Oregon

14

Resurvey of West Bdy., T. 32 S., R. 9W.

CHAINS

Land, mountainous.

Soil, stony clay loam, 2nd and 3rd rate.

Timber, fir, cedar, sugar pine and laurel.

Undergrowth, rhododendron, chinquapin, tan oak, laurel, and vine maple.

N.0°38'W., surveying W. bdy. of sec. 6.

Ascend S. slope, through heavy timber and dense undergrowth.

10.25 Top of ridge, bears NW. and SE.; descend.

19.75 Across slide.

26.50 Leave slide; along E. slope.

29.15 Intersect the old $\frac{1}{4}$ sec. cor., which is a basalt stone, 18x10x7 ins., loosely set, marked and witnessed as described by the surveyor general. I change this cor. to refer to sec. 1 only and perpetuate it as follows: alongside the old cor.

Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ cor. of sec. 1, T.32 S., R. 10 W. only, with brass cap marked

$\frac{1}{4}$
S1
1917

from which

A sugar pine, 12 ins. diam., bears S.71°W., 41 lks. dist., marked $\frac{1}{4}$ S 1 B T (New B.T.)

A hemlock, 5 ins. diam., bears N.62°W., 16 lks. dist., marked $\frac{1}{4}$ S 1 B T (New B.T.)

Thence

N.0°09'W., continuing my measurements.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ cor. of sec. 6 only, with brass cap marked

$\frac{1}{4}$
S6
1917