

County Surveyor's Record, Douglas County, Oregon

19

Subdivisions, T. 32 S., R. 9 W.

CHAINS

Land, mountainous.

Soil, stony clay loam and shale, 2nd, 3rd and 4th rate.

Timber, fir, cedar, sugar pine and laurel.

Undergrowth, chinquapin, rhododendron, tan oak, hazel and buckhorn.

N.89*56'E., on a random line, bet. secs. 24 and 25.

40.00 Set temp. $\frac{1}{2}$ sec. cor.

78.87 Intersect the E bdy. of the Tp., 2 lks. S. of the cor. of secs. 24 and 25.

Thence

S.89*55'W., on a true line, bet. secs. 24 and 25.

Ascend through heavy timber and dense undergrowth.

11.35 Ravine, course SE.; ascend.

25.20 Top of ridge, bears N. and S.; descend.

Trail along ridge, bears N. and S.

38.87 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{2}$ sec. cor., with brass cap marked,

$$\frac{\frac{1}{2} \text{ S24}}{\text{S25}} \\ 1917$$

from which

A fir, 16 ins. diam., bears S.40*W., 47 lks. dist., marked $\frac{1}{2}$ S 25 B T.A fir, 36 ins. diam., bears N.70*W., 45 lks. dist., marked $\frac{1}{2}$ S 24 B T.

44.95 Creek, 2 lks. wide, course SW.; along S. slope.

50.20 Creek, 2 lks. wide, course S.; ascend.

61.85 Ravine, course SE.

78.87 The cor. of secs. 23,24, 25 and 26.

Land, mountainous.

Soil, stony clay loam, and shale rock, 3rd and 4th rate.

Timber, fir and sugar pine.

Undergrowth, tan oak, buckhorn, fir and live oak.